## PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is certified that an Inspection team headed by Mr.Ranjith Kumar, SANITARY INSPECTOR (Name of officer and with designation) from , DINDIGUL CITY MUNICIPAL CORPORATION, DINDIGUL , DINDIGUL District, Tamilnadu inspected the ST.JOSEPH'S SCHOOL, Y.M.R. PATTY, DINDIGUL – 624001 (Name and address of the school) on 27.12.2024 (date of the inspection ) and on the basis of Water Testing report (Attached)no. bearing TR/2023/2435-B2436 District Water Testing Laboratory, (PHED Lab ) certified that the ST.JOSEPH'S SCHOOL (Name of the school) has safe drinking water facilities for the student and members of the staff of the institution. School is also maintaining the hygienic condition in the school building and the campus as per norms prescribed by the Central / State / U.T Govt.

This certificate is valid till 26-12-2025. (ONE YEAR FROM THE DATE OF ISSUE)

SANITARY INSPECTOR TIME DINDIGUL CITY MUNICIPAL CORPORATION Signature with seal

Name: Mr.Ranjith Kumar

**Designation: SANITARY INSPECTOR** 

Name and address of the office /Department: DINDIGUL CITY MUNICIPAL CORPORATION,
DINDIGUL.

To

ST.JOSEPH'S SCHOOL, Y.M.R.PATTY, DINDIGUL - 624001.

PRINCIPAL
St. Joseph's School
Y.M.R Patty, Dindigul-1



### TAMILNADU WATER SUPPLY AND DRAINAGE BOARD

### DISTRICT WATER TESTING LABORATORY

Vadamadurai Cauvery Water Pump House Campus, Vadamadurai, Dindigul-624802.

Phone: 0451 - 2410188

E-mail: wtldgl17@gmail.com

		TEST REPORT	Doc.No: DWTL/FORM/7.8	
Report No:	TR/2023/ 2435-B2436	Report Issue Date:	15.12.2023	Page No:01 of 02
Invoice Details:	728/Dt.08.12.2023 Amt.Rs.1652/-			
Client Name & Address Contact No / Email.ID		The Correspondent, St.Joseph's School, Y.M.R Patty, Dindigul - 624001, 9942206607.		

	9942206607.	
Sample Name	: Water	
Sample Number	: 2435-B2436	
Sample Description	: Municipality Water(Reverse Osmosis)	
Sample Submitted by	: Customer	
Location & Date	: St.Joseph's School, Y.M.R Patty & 08.12.2023	
Quantity of sample Received	: 2 Litre	
Sample Container	: Jerry Cane	
Sample Condition on Receipt	: Good	
Sample Received On	: 08.12.2023	
Test Commenced on	: 09.12.2023	
Test Completed on	: 15.12.2023	
- 1 10 111	22 000 22 000	

S. No			Unit	Result	Specification as per IS 10500 : 2012(RA:2019)		
	Parameters	Test Method			Acceptable Limit	Permissible Limit in the absence of alternate source	
PHY	SICAL & CHEN	MICAL EXAMINATION:					
1	Appearance	Visual observation		Clear	Clear	Clear	
2	Colour	APHA 23 <sup>rd</sup> Edition 2017 4500 H+ B	Hazen	< 5	1	5	
3	Odour	IS 3025 Part 5 : 1983		Agreeable	Agreeable	Agreeable	
4	Turbidity	APHA 23rd Edition 2017 - 2130 B	NTU	< 0.5	1	5	
5	Total Dissolved Solids	APHA 23rd Edition 2017 – 2540 C	mg/L	96	500	2000	
6	Conductivity	APHA 23rd Edition 2017 - 2510 B	μS/cm	174		-	
7	Iron as Fe	APHA 23rd Edition 2017- 3500 Fe B	mg/L	< 0.1	0.3	1	
8	Residual Chlorine	IS/APHA	mg/L	0	0.2	1.0	
BAC	CTERIOLOGICA	L EXAMINATION:					
9	Fecal Coliform	IS/APHA	CFU/ 100ML	0	0	0	

Remark: The tested sample confirmed to IS:10500:2012(RA:2019)Drinking water specification with respect to above tested parameters.

Authorised Signatory
R.Amsapriya
Assistant Engineer

### Note:

1. The test results relate only to the items tested.

2. The test report shall not be reproduced anywhere except in full and in the same format without the permission of the laboratory.

3. Unless informed by systemer, the test items will not be retained for more than 15 days from the date of issue of the test report.

4. The result applied to the sample as received basis.

PRINCIPAL

ST.JOSEPH'S SCHOOL

Y.M.R Porty, Dindigul-1

CORRESPONDENT ST.JOSTOR'S SCHOOL

Y.M.R Patty, Dindigul-1



Phone: 0451 - 2410188

# LAMILAND WALLESTED FAVOR REVES BOOKS

# DISTRICT WATER HISTING LABORATORS

Vadamadurai Canvery Water Pump House Campus, Vadamadurai. Dindigul-624802

I mail wildell a gmail com



## TEST REPORT

Doc No. DWIL FORM 7 8:01

Report No:	TR/2023/ 2435	Report Issue Date :	[15.12.2023   Page No : 01 of 01
Invoice Details:	728/Dt.08.12.2023	ULR No	1C104162300000150F

7Min. 183. 10.22	
Client Name & Address Contact No / Email.ID	: The Correspondent, St.Joseph's School. Y.M.R Patty. Dindigul - 624001, 9942206607.
Sample Name	: Water
Sample Number	: 2435
Sample Description	: Municipality Water(Reverse Osmosis)
Sample Submitted by	: Customer
Location & Date	: St.Joseph's School, Y.M.R Patty & 08.12.2023
Quantity of sample Received	: 2 Litre
Sample Container	: Jerry Cane
Sample Condition on Receipt	: Good
Sample Received On	: 08.12.2023
Test Commenced on	: 09.12.2023
Test Completed on	: 15.12.2023
Environmental Condition	: 23.0°C - 27.0°C

231111111	Parameters	Unit	Test Method	Result	Specification as per IS 10500:2012(RA:2019)	
S.No					Acceptable Limit	Permissible Limit in the absence of alternate source
1	pH a 25° C .	-	1S 3025 Part 11-1983	7.04	6.5-8.5	6.5-8.5
2	Total Hardness as CaCO <sub>3</sub>	mg/L	18 3025 Part 21-2009	48	200	600
3	Total Alkalinity as CaCO <sub>3</sub>	mg/L	1S 3025 Part 23-1986	68	200	600
4	Chloride as Cl	mg/l	1S 3025-Part 32-1988	33	250	1000
5	Sulphate as SO4	mg/L	18 3025-Part 24-1986	- 5	200	4()()
6	Nitrate as NO <sub>3</sub>	mg/L	APHA 23rd Edition 2017 4500 NO3 B	<2	45	45
7	Fluoride as F	mg/I	APHA 23rd Edition 2017 4500- F-D	0.49	1.0	1.5
					1.1	L

Remark: The tested sample confirmed to IS:10500:2012(RA:2019)Drinking water specification with respect to above tested parameters.

.....End of the report......

Authorised Signatory R.Amsapriya

Assistant Engineer

#### Note:

1. The test results relate only to the items tested.

The test report shall not be reproduced anywhere except in full and in the same format without the permission of the laboratory

3. Unless informed by customer, the test items will not be retained for more than 15 days from the date of issue of the test report.

4. The result applied to the sample as received basis.

ST.JOSEPH'S SCHOOL M.R Patty, Dindigul-1

ST.JOSEPH'S SCHOOL Y.M.R Patty, Dindigul-1